Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L40	1641	(((temperature or thermal) near (exceed\$ or threhsold or overload\$ or maximum)) with (indicat\$ or alarm\$ or warn\$ or alert\$)).detd.	USPAT	OR	OFF	2005/03/19 18:24
L41	1	40 and ((detect\$ or monitor\$ or sens\$) near lambda).detd.	USPAT	OR	OFF	2005/03/19 18:27
L42	· . 0	40 and ((vehicle or car or automobile) with lambda).detd.	USPAT	OR	OFF	2005/03/19 18:27
L43	0	40 and ((vehicle or car or automobile) same lambda).detd.	USPAT	OR	OFF	2005/03/19 18:27
L44	966	((detect\$ or monitor\$ or sens\$) near lambda).detd.	USPAT	OR 🐇	OFF	2005/03/19 18:29
L45	23	44 and ((alarm\$ or indicat\$ or alert\$ ro warn\$) near lambda).detd.	USPAT	OR	OFF	2005/03/19 18:36
L46	905	(indicator\$ with chang\$ with (heat or temperature)).detd.	USPAT	OR	OFF	2005/03/19 18:36
L47	83620	"340"/\$.ccls.	USPAT	OR	OFF	2005/03/19 18:37
L48	48	46 and 47	USPAT	OR ·	OFF	2005/03/19 18:48
L49	23	("4371827").URPN.	USPAT	OR	OFF	2005/03/19 18:47
L50	14439	(material with chang\$ with (heat or temperature or thermal)).detd.	USPAT	OR	OFF	2005/03/19 18:49
L51	1478	50 and ((indicat\$ or warn\$ or alert\$ or alarm\$) near2 (heat or thermal or temperature)).detd.	USPAT	OR	OFF	2005/03/19 18:53
L52	19	51 and ((indicat\$ or warn\$ or alert\$ or alarm\$) with (screw or nut)). detd.	USPAT	OR	OFF	2005/03/19 18:52
L53	491	50 and ((indicat\$ or material) with (screw or nut)).detd.	USPAT	OR	OFF	2005/03/19 18:53
L54	49	53 and 51	- USPAT -	OR	OFF	2005/03/19 18:53
L55	31	54 not 52	USPAT	OR	OFF	2005/03/19 19:01
L56	24	("2870316" "3802945"	US-PGPUB;	OR	OFF	2005/03/19 18:57
		"3822594" "3959787" "3965742" - "4102300" "4180043"	USPAT;			
		"4102200" "4189942" "4351996" "4649854" "4682857"	USOCR			
		"4738549" "4751912" "4806858" "4983810" "5315956"				
		"5482373" "5499597" "5543246" "5750959" "5767489" "5786578" "5997964"				
		"6104007").PN.			Angel	
L57	120	(219/445.1).CCLS.	USPAT	OR	OFF	2005/03/19 19:04
L58	13794	"374"/\$.ccls.	USPAT:	OR -	OFF	2005/03/19 19:04

	· · · · · · · · · · · · · · · · · · ·	r				
L59	5332	58 and (indicat\$ or alarm\$ or warn\$ or alert\$ or (chang\$ near color\$1)). detd.	USPAT	OR	OFF	2005/03/19 19:16
L60	366	59 and (vehicle or car or automobile).detd.	USPAT	OR	OFF	2005/03/19 19:06
L61	12	60 and lambda.detd.	USPAT	OR	OFF	2005/03/19 19:06
L62	17	("4501145").URPN.	USPAT	OR	OFF	2005/03/19 19:13
L63	7	("4658632").URPN.	USPAT	OR	OFF	2005/03/19 19:15
L64	112608	"73"/\$.ccls.	USPAT	OR	OFF	2005/03/19 19:15
L65	4655	64 and ((indicat\$ or alarm\$ or warn\$ or alert\$ or (chang\$ near color\$1)) with (temperature or thermal or heat)).detd.	USPAT	OR	OFF	2005/03/19 19:16
L66	20	65 and ((temperature or heat or thermal) near2 lambda).detd.	USPAT	OR	OFF	2005/03/19 19:16
L67	17	66 not 61	USPAT	OR	OFF	2005/03/19 19:23
L68	1154	(46 or 58 or 64) and (((thermal or heat or temperature) with (indicat\$ or sens\$ or alarm\$ or warn\$ or alert\$)) and (material with (chang\$ or melt\$) with (thermal or heat or temperature))).detd.	USPAT	OR.	OFF	2005/03/19.19:25
L69	14	68 and ((oxidation or oxidiz\$) and (chemical near chang\$)).detd.	USPAT	OR	OFF	2005/03/19 19:26
L70.	29	68 and ((oxidation or oxidiz\$) and (chemical near (chang\$ or reaction))).detd.	USPAT	OR	OFF	-2005/03/19 19:28
L71	7	70 and alloy	USPAT	OR	OFF	2005/03/19 19:27
L72	2	-71 and ceramic	USPAT	OR	OFF.	2005/03/19 19:27
L73	181	68 and (oxidation or oxidiz\$ or (chemical near (chang\$ or reaction))).detd.	USPAT	OR	OFF	2005/03/19 19:28
L74	24	73 and (vehicle or car or automobile).detd:	USPAT	OR	OFF	2005/03/19 19:29